Public Document Pack



Contact: Democracy@enfield.gov.uk

ENVIRONMENT FORUM

Tuesday, 25th April, 2023 at 7.00 pm in the Council Chamber, Civic Centre, Silver Street, Enfield, EN1 3XA

SUPPLEMENTARY AGENDA

6. HERITAGE (Pages 1 - 24)

To receive a presentation on Heritage.

This page is intentionally left blank

Heritage at Risk

Environment Forum

25 April 2023

www.enfield.gov.uk

Striving for excellence



Heritage at Risk Register

- First compiled in 1990s by Historic England and Local Planning Authorities.
- Sites most at risk of being lost through neglect, decay or inappropriate development.
- Updated annually by Historic England
- Tool to focus priorities and support funding bids





Heritage at Risk Register

The Register includes:

- Listed Buildings
- Scheduled Monuments
- Registered Parks and Gardens
- Registered Battlefields
- Protected Wrecks
- Conservation Areas





Heritage at Risk Register

Listed Buildings

- Condition
- Priority Category for action on a scale of A (highest) to F (lowest).

Conservation Areas, Scheduled Monuments and Registered Parks and Gardens

- Condition 'Very Bad', 'poor', 'fair' and 'optimal'
- Vulnerability. 'high', 'medium' or 'low'
- Trend 'declining', 'stable', 'improving' or 'unknown'

INFIELD					
3	STENANE	Holly Hill Farmhouse, The Ridgeway	Mid C19 villa of London stock brick, formerly a farmhouse, with later additions and outbuildings to the rear. The house		
	DESIGNATION	Listed Building grade II	has been vacant for many years and has suffered from the effects of water ingress, blocked rainwater goods,		
2 S I S S	CONDITION	Very bed	vegetative growth, broken windows and rotten joinery.		
COLUMN STATE	OCCURANCY:	Vacant/not in use	The building is now secured, and Historic England and the Local Authority have identified urgent works needed to		
Contraction of the second	PROMITY CATROOMS	A (A)	arrest further decline whilst a decision is made on the future use of the building.		
	OWNERTON	Local authority	future use of the building.		
Phane's England	LET INTER NUMBER	1188655	Contact: Christine White (LPA) 020 8379 3852		
	SITE NAME:	North Lodge, Whitewebbs	Small Victorian Gothic stuccoed cottage of one storey and		
the states		Road	an attic, with a steep-pitched roof of fishscale tiles with barge-boarded gable ends. The building has been empty		
1000000	DESIGNATION	Listed Building grade II	and neglected for many years and part of the building has now been subject to unauthorised demolition works. The		
the Content of States	CONDITION	Very bad	 Local Authority has undertaken extensive works to secure 		
Contraction of the local division of the loc	DCCUPANCY	Vacant/not in use	and protect the building under enforcement regulations.		
S	PROATY CATEGORY	A.(A)	Steps are now being taken to ensure appropriate consents are obtained, and full repair of the building secured.		
Contraction in the local division of the loc	OWNER TYPE	Private			
Country Records of Dolaid	LET IN THE NUMBER	1079477	Contact: Christine White (LPA) 020 8379 3852		
	SITE NAME:	Southgate House, High Street	Late C18 house with early C19 extension in similar style, with an elliptical entrance hall. Formerly used as a college, it		
	DESIGNATION	Listed Building grade II*	is now vacant whilst a new use is secured. Water ingress,		
- PER L	CONDITION	Poor	I now halted, has led to outbreaks of dry not, and vegletation growth has humpered versitiation and drainage to the building. The building was sold in 2020. The Local Authority and Historic England are working with the new owner to bring forward a suitable proposal to secure its future. Some works have been carried out but further works are needed to trabilities the building.		
	DCCLEMICT.	Vacant/not in use			
	PROATY CATROOM	C (A)			
	OWNERTON	Local authority			
Planetic Regional	LET INTER INCOME.	1079541	Contact: Verena McCaig 020 7973 3718		
Passero Engand			Construction and a construction of the		
13 M	STENANE	Broomfield House, Broomfield Park, Broomfield Lane N13	C16 house with late C18 additions, stuated in a public park. The building is sevenity fire damaged, although significant parts of the interview in a test storage. Additional scaffolding works were carried out in 2016 funded by Hustoric English and the Local Authority.		
-	DESGNATION	Listed Building grade II*, RPG grade II			
AND DESCRIPTION OF THE OWNER OF	CONDITION	Very bad	Following extensive discussions and commissioned report further work is being carried out to help inform a decision		
and a second sec	DCCUPANCY	Vacant/not in use	on the future of the building.		
No. of Concession, Name	PROATY CATEGORY	A.(A)			
Phantic England	OWNER TYPE	Local authority			
And a second second	LET DATRY NUMBER:	1078934	Contact: Verena McCaig 020 7973 3718		
	STENAME	Stable block in Broomfield Park, Broomfield Lane N13	Early C18 stable block to Broomfield House. The buildin is vacant. Internal propping works have been undertaken		
STATE TRUE	DESCRIPTION	Listed Building grade IP, RPG grade II	stabilise the floors, and further works carried out following subsequent fire and water damage. Following extensive discussions and commissioned reports, further work is		
And Designed	CONDITION	Very bad	being carried out to help inform a decision on the future of		
	DCCUPANCE	Vacant/not in use	the building.		
Same S	PROMITY CATEGORY	A (A)			
T. S. P. Martin	OWNER TYPE:	Local authority			
Heboric England	LST INTRY NUMBER	1188544	Contact: Verena McCaig 020 7973 3718		
NORITY CATEGORIES	D Slow decay, solution	agreed but F. Repar scheme to progress a	nd NOTE CA Createration Area		
deterioration or loss of falses; no polytics agreed. Immediate rais of further rapid deterioration or loss of falses; subdim agreed lust rust yet implemented. Show desay; no subdim agreed.	mot yet implementer E Under repair an in 5 repair, but na users under threat of vacs statutes new user (a to facilities capatite under.).	iar to good User identified; or functional sheetified; or restandant liabilings with ne accredit to agreed lost net pet implement			



Page 4

Heritage at Risk, London

- Enfield is at the London average, 20 entries
- Worst Hillingdon 43 entries
- Best City of London 2 entries.
- The average is 19.

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
GREATER LONDON							
Barking and Dagenham	4	1	1	0	0	0	1
Barnet	4	4	1	0	0	0	1
Bealey	3	0	0	0	0	0	0
Brent	7	3	0	0	0	0	0
Bromley	19	1	3	1	0	0	1
Canden	17	14	0	0	0	0	0
City of London	0	2	0	0	0	0	0
Croydon	6	5	2	0	0	0	1
Ealing	7	1	2	0	0	0	5
Enfield	11	2	1	4	0	0	2
Greenwich		2	a		0	0	2
Hackney	20	11	0	1	0	0	2
Hammerumith and Fulham	12	1	a	0	0	0	1
Haringey	11	5	0	0	0	0	5
Harrow	12	1	5	1	0	0	0
Havering	9	0	1	0	0	0	1
Hilington	29	2	3	0	0	0	9
Houndow	20	1	2	1	0	0	2
kingon	12	9	0	0	0	0	10
Kensington and Chelsea	31	4	0	1	0	0	1
Kingston upon Thames	5	1	0	0	0	0	3
Lambeth	26	1	0	0	0	0	3
Lewisham	16	2	0	0	0	0	1
London Legacy (MDC)	4	0	0	0	0	0	2
Merton	14	0	1	1	0	0	6
Newham	13	0	0	0	0	0	0
Redbridge	3	2	0	1	0	0	3
Richmond upon Thames	15	0	a	0	0	0	1
Southwark	25	4	2	1	0	0	2
Sutton	5	1	0	0	0	0	1
Tower Hamiets	22		1	0	0	0	5
Waltham Forest	12	4	0	0	0	0	0
Wandsworth	7	0	0	0	0	0	0
Wedminder, City of	12	9	0	0	0	0	0



Heritage at Risk, Enfield

2022 Heritage at Risk Register

- 11 Buildings and Structures
- 2 Places of Worship
- 1 Archaeological Site
- 4 Parks and Gardens
- 2 Conservation Areas
- Common reasons are ownership, unused, management regimes.
- Tools are 'Carrot & Stick'. Urgent Works Notice, Repairs Notice / CPO, partnership brokering
- Active on most entries.






Enfield Heritage at Risk Action Plan

Enfield Heritage Strategy 2019-24 (Objective 4)

- "Work with property owners and Historic England to secure repairs and identify opportunities for adaptation and sustainable use"
- "Maintain an up-to-date Heritage at Risk register and make annual contact with owners to monitor progress"





Charity School and No.24 Church Street

- LHBT working with Learning for Life Charity
- Learning and training opportunities for young people in Enfield with special educational needs / disadvantaged and a community hub.
- Funding. £300k from Lottery and £33k from AHF for development phase (design, activities, business plan 12 months)
- Application for delivery phase May 24 (capital work & operational phases). Completion 2026.
- Meanwhile use of artist studios in partnership with the Florence Trust.
- Brokered partnerships, on Project Board, support of Historic England and Enfield Society..




<u>LHBT press release:</u> <u>https://londonhistoricbuildings.org.uk</u>



Trent Park Terrace

- Part of the Berkley Homes redevelopment of the former Middlesex University Campus.
- Berkeley programme Spring 2024





Southgate House

- Inspection with Historic England 2022.
- Prepared schedule of repairs and pursued with owner (pre cursor to UWN)
- Change of ownership in 2023.
- Land Registry search to open engagement with new owner





Whitewebbs Barn

- Consent for residential conversion and enabling development
- Applications to discharge conditions have been received

North Lodge

- Stabilising Works carried out in default
- New owners Tottenham Hotspur FC
- Plans to restore

Enfield Electricity Works

- UK Power Networks sub station
- Secured structural repairs 2014
- Brokering interest from local enterprises





Buildings & Structures (Ownership: Council)

Holly Hill Farmhouse

- Funding identified for repair
- Updated survey 2023
- Timetable for works to follow
- Site inspection with Historic England and LBE Property Team Spring 2023

Lavender Hill Cemetery Chapel

• Site inspection with Historic England, and LBE Property Team Spring 2023








Buildings & Structures (Ownership: Council)

Broomfield House and Broomfield Stables

- NHLF Round 1 bid due for submission Aug 23 for dismantlement & memorialisation of the House plus revitalising historic elements of the baroque park.
- On successful awarding of grant funding, current programming sees the delivery of these works in 2026.
- The Stable Block will follow the Broomfield House phase.





Parks & Gardens

Common issues

- Landscape design intentions no longer visible
- Encroachment low value self seeded vegetation onto key vistas and areas of open parkland
- Planting in inappropriate locations
- Interventions in inappropriate locations
- Split ownership and management with other organisations eroding significance as a single heritage asset,





Parks & Gardens (Ownership: Council)

Trent Park

- Site meeting with Historic England and LBE Parks Team March 2023.
- Steering Group set up / Festival programme funding towards management plan
- Introduction of cattle to assist with parkland management (after Forty Hall pilot)
- On-going discussions with Berkeley Homes regarding the restoration of the landscape., including north lake edge works..





Parks & Gardens (Ownership: Council)

Broomfield Park

- NHLF Round 1 bid due for submission Aug 23 for revitalising historic elements of the baroque park.
- On successful awarding of grant funding, current programming sees the delivery of these works in 2026

Forty Hall

- Site visit with Historic England and LBE Parks Team March 2023.
- Introduction of cattle to assist with parkland management (4ha pilot, 14ha expansion). From late May 23.

Grovelands Park

 Divided ownership LBE, Thames Water& The Priory






Archaeological Sites (Ownership:Council)

Site of Elsynge Hall

- Site meeting with Historic England and LBE Parks Team March 2023.
- Signage for prevention of metal detecting.
- Introduction of cattle to assist with parkland management.





Places of Worship

Supporting funding applications for repair and usage

All Saints, Edmonton



Church of St Andrews, Enfield





Conservation Areas

Church Street and Fore Street

- 'Averaging up' the quality of approved applications.
- Secured financial contributions from Edmonton Green redevelopment for heritage enhancements.





Any Questions ?



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Page 21

Southgate House, High Street

Broomfield House, Broomfield

Park, Broomfield Lane NI3

Listed Building grade II*, RPG

Listed Building grade II*

Vacant/not in use

Local authority 1079541

NI4

Poor

C (A)

grade II

A (A)

1078934

Very bad

Vacant/not in use

Local authority



SITE NAME:	Holly Hill Farmhouse, The Ridgeway	Mid C19 villa of London stock brick, formerly a farmhouse, with later additions and outbuildings to the rear. The house
DESIGNATION:	Listed Building grade II	has been vacant for many years and has suffered from the effects of water ingress, blocked rainwater goods,
CONDITION:	Very bad	vegetative growth, broken windows and rotten joinery. The building is now secured, and Historic England and the
OCCUPANCY:	Vacant/not in use	Local Authority have identified urgent works needed to arrest further decline whilst a decision is made on the
PRIORITY CATEGORY:	A (A)	future use of the building.
OWNER TYPE:	Local authority	-
LIST ENTRY NUMBER:	1188655	Contact: Christine White (LPA) 020 8379 3852

© Historic England



SITE NAME:	North Lodge, Whitewebbs Road	Small Victorian Gothic stuccoed cottage of one storey and an attic, with a steep-pitched roof of fishscale tiles with				
DESIGNATION:	Listed Building grade II	barge-boarded gable ends. The building has been empty and neglected for many years and part of the building has				
CONDITION:	Very bad	now been subject to unauthorised demolition works. The Local Authority has undertaken extensive works to secure				
OCCUPANCY:	Vacant/not in use	and protect the building under enforcement regulations.				
PRIORITY CATEGORY:	A (A)	Steps are now being taken to ensure appropriate consents are obtained, and full repair of the building secured.				
OWNER TYPE:	Private					
LIST ENTRY NUMBER:	1079477	Contact: Christine White (LPA) 020 8379 3852				

Late C18 house with early C19 extension in similar style,

is now vacant whilst a new use is secured. Water ingress,

owner to bring forward a suitable proposal to secure its

future. Some works have been carried out but further

CI6 house with late CI8 additions, situated in a public

park. The building is severely fire damaged, although

Additional scaffolding works were carried out in 2016

further work is being carried out to help inform a decision

funded by Historic England and the Local Authority. Following extensive discussions and commissioned reports,

significant parts of the interior are in safe storage.

building. The building was sold in 2020. The Local Authority and Historic England are working with the new

works are needed to stabilise the building.

Contact: Verena McCaig 020 7973 3718

Contact: Verena McCaig 020 7973 3718

on the future of the building.

with an elliptical entrance hall. Formerly used as a college, it

now halted, has led to outbreaks of dry rot, and vegetation growth has hampered ventilation and drainage to the

© London Borough of Enfield



© Historic England



© Historic England



			C C			
SITE NAME:		Stable block in Broomfield Park, Broomfield Lane N13	Early C18 stable block to Broomfield House. The building is vacant. Internal propping works have been undertaken t			
	DESIGNATION:	Listed Building grade II*, RPG grade II	stabilise the floors, and further works carried out following subsequent fire and water damage. Following extensive discussions and commissioned reports, further work is being carried out to help inform a decision on the future o the building.			
i.	CONDITION:	Very bad				
	OCCUPANCY:	Vacant/not in use				
	PRIORITY CATEGORY:	A (A)				
	OWNER TYPE:	Local authority				
	LIST ENTRY NUMBER:	1188544	Contact: Verena McCaig 020 7973 3718			

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / LONDO	on and south east	/ ENFIELD Page 22			
	SITE NAME:	Nonconformist Chapel, Lavender Hill Cemetery, Cedar Road	1870-1 Gothic Revival cemetery chapel. The chapel is in poor condition and in need of an appropriate use. Repairs are required to arrest deterioration of damaged stonework		
	DESIGNATION:	Listed Building grade II	and a decision is needed on the future of the building.		
	CONDITION:	Poor			
Carlos I a Maria	OCCUPANCY:	Vacant/not in use			
	PRIORITY CATEGORY:	C (C)			
and a second	OWNER TYPE:	Local authority			
© Historic England	LIST ENTRY NUMBER:	1079458	Contact: Christine White (LPA) 020 8379 3852		
	SITE NAME:	Former Edmonton Girls' Charity School, Church Street, Edmonton N9	Single-storey building, with a central arched doorway to the street and sash windows to either side. Above the doorway is a statuette of a female pupil. Historic England		
	DESIGNATION:	Listed Building grade II, CA	and the Local Authority are working with the current owners and London Historic Buildings Trust to secure a		
	CONDITION:	Poor	repair project. Potential new users have been identified an discussions are ongoing to identify funding sources. In the meantime, live-in guardians continue to safeguard the		
	OCCUPANCY:	Part occupied/part in use			
	PRIORITY CATEGORY:	C (C)	property.		
	OWNER TYPE:	Religious organisation			
© Historic England	LIST ENTRY NUMBER:	1079547	Contact: Christine White (LPA) 020 8379 3852		
	SITE NAME:	24, Church Street, Edmonton N9	Former teacher's accommodation to the adjoining Charity School. C18 cottage of red brick with renewed pantile		
	DESIGNATION:	Listed Building grade II, 2 CAs	roof. Historic England and the Local Authority are working with the current owners and London Historic Buildings		
	CONDITION:	Poor	Trust to secure a repair project. Potential new users have been identified and discussions are ongoing to identify		
	OCCUPANCY:	Occupied/in use	funding sources. In the meantime, live-in guardians continue		
	PRIORITY CATEGORY:	C (C)	to safeguard the property.		
	OWNER TYPE:	Religious organisation			
© Historic England	LIST ENTRY NUMBER:	1079546	Contact: Christine White (LPA) 020 8379 3852		
Share 12	SITE NAME:	Trent Park House terrace, Cockfosters Road, Trent Park	Brick and stone terrace reconstructed in the 1920s. The terrace is in very poor condition, with temporary propping in place. Vegetation clearance and further propping works		
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	were undertaken after additional surveys were carried out in 2015. Full repair and conservation are expected to take		
	CONDITION:	Very bad	place as part of the planned redevelopment of the wider site, which is in progress.		
	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	D (D)			
© Llisteria England	OWNER TYPE:	Commercial company			
© Historic England	LIST ENTRY NUMBER:	07893	Contact: Christine White (LPA) 020 8379 3852		
	SITE NAME:	Enfield Electricity Works, 20, Ladysmith Road, Enfield	Former Enfield Electricity Works dating from 1906, architect unknown. The building is partially occupied.		
	DESIGNATION:	Listed Building grade II	Extensive works have been undertaken to stabilise the building and make it watertight. However, further works		
	CONDITION:	Poor	are required to the exterior tile-work and masonry to prevent water ingress and further damage. Future		
	OCCUPANCY:	Part occupied/part in use	operational options are under consideration for the site		
	PRIORITY CATEGORY:	C (C)	which will inform its future repair and re-use.		
	OWNER TYPE:	Utility			
© Historic England	LIST ENTRY NUMBER:	1389537	Contact: Christine White (LPA) 020 8379 3852		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Barn at Whitewebbs Farm,	Simple timber fr	ramed barn probably dating from the late	
1 THE DE	SHE MALLE:	Whitewebbs Road	CI7. Works hav	ture. Planning Permission and Listed	
	DESIGNATION:	Listed Building grade II	Building Consent	t have been granted for residential	
	CONDITION:	Very bad	conversion. Plan and works have	ning conditions have yet to be discharged yet to commence on site.	
	OCCUPANCY:	Vacant/not in use	,		
	PRIORITY CATEGORY:	B (B)			
	OWNER TYPE:	Private			
D London Borough of Enfield	LIST ENTRY NUMBER:	1079480	Contact: Christin	ne White (LPA) 020 8379 3852	
T T	SITE NAME:	All Saints Church, Church Street, Edmonton N9	C12 in origin, largely rebuilt in the C15 and clad in brick 1772. Restored in 1855 and 1871 by Ewan Christian an		
	DESIGNATION:	Listed Place of Worship grade II*, CA	1889 by William Gillbee Scott. The church has a K ragstone medieval tower, 1772 brick-faced east ar sides, and stone south and west sides. The church		
1.0 00-1	CONDITION:	Poor	awarded a grant from the National Lottery Heritage F for repair works to the tower which were completed early 2016. The nave and aisle roofs are in need of re- covering. A fall of stone internally necessitated general investigations and temporary holding repairs until a scl		
	PRIORITY CATEGORY:	C (C)			
	OWNER TYPE:	Religious organisation			
	LIST ENTRY NUMBER:	1079548	of work can be p	prepared.	
© Colin Kerr (Architect)			Contact: Tracey	Craig 020 7973 3756	
	SITE NAME:	Church of St Andrew, Church Walk, Enfield	The church and tower have C12 origins, were extend C15 and C16 (Sir Thomas Lovell), repaired in C18, an		
	DESIGNATION:	Listed Place of Worship grade II*, CA	restored in C19 (including all new roofs) by variously Lochner, St Anbyn and Scott. It is built of rubble may including brick and flint with stone quoins and windo dressings. There are fine C15 and C16 monuments I these are deteriorating due to dampness caused by J drainage. The leaking tower roof has caused a struct failure in the belfry. Holding repairs are in place and Parish is seeking funding for a comprehensive develo		
Philes	CONDITION:	Very bad			
	PRIORITY CATEGORY:	A (A)			
State Proved	OWNER TYPE:	Religious organisation			
	LIST ENTRY NUMBER:	1079549	and repair project		
∋ Historic England			Contact: lan Har	-per 020 7973 3786	
SITE NAME:	Site of Elsynge H	all, Forty Hall			
DESIGNATION:	Scheduled Monur	nent, part in RPG grade II, CA	LIST ENTRY NUMBER:	1002040	
CONDITION:	Generally satisfac problems	Generally satisfactory but with significant localised		Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growt	th	NEW ENTRY?:	Yes	
OWNER TYPE:	Local authority, n	nultiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145	
The second of	SITE NAME:	Broomfield Park N13	Early C18 forma	l gardens associated with Broomfield	
	DESIGNATION:	Registered Park and Garden grade II, 4 LBs, part in CA	of formal lakes, a for use as a publ	ng a walled enclosure focussed on a serie and set within a landscape park. Converte ic park in the early C20, with input from	
	CONDITION:	Generally satisfactory but with significant localised problems	historic parkland	n. The lakes are in poor condition and the has suffered losses to development. The block are in very bad condition and	
the states and	VULNERABILITY:	Medium	further work is b	eing carried out to help inform a decisior the buildings. A Conservation Manageme	
and the second lines	TREND:	Declining	Plan exists for th	e landscape and discussions are needed t	
	NEW ENTRY?:	No	secure its implementation.		
Historic England Archive	OWNER TYPE:	Local authority			
	LIST ENTRY NUMBER:	1000517		opher Laine 020 7973 3473	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Grovelands Park N14	l ate CI8 lande	scape park and lake by Humphry Repton,
	DESIGNATION:	Registered Park and Garden grade II*, 5 LBs, part in CA	extended in th the early C20	e mid-C19 and late by fulfiping reptor, by Thomas Mawson. The mansion and unds are now a private hospital. The divided
- Palate	CONDITION:	Generally satisfactory but with significant localised problems	ownership of t Thames Wate	he park between the Local Authority, r and the hospital has led to differential
Les Rail	VULNERABILITY:	Medium	condition with	egimes. The sports area is in very bad intrusive fencing and redundant structures.
and all a started	TREND:	Declining	A Conservatio	n Management Plan requires completion an e needed in order to then secure its
A STATISTICS	NEW ENTRY?:	No	implementatio	
Historic England Archive	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1000395	Contact: Christopher Laine 020 7973 3473	
	SITE NAME:	Trent Park	Late C18 lands	scape park further developed in the early
All and a start of	DESIGNATION:	Registered Park and Garden grade II, 19 LBs, SM, part in CA	C20 by Sir Philip Sassoon. Developers are impler their approved scheme for improvements to the the historic landscape around the mansion house	
	CONDITION:	Generally satisfactory but with significant localised problems	owned and ma	ant issues in the surrounding parkland, anaged by the Local Authority as a country ons continue towards improving the inter-
TO PARA	VULNERABILITY:	Medium	relationship be	etween the wider park and the historic core
all I and	TREND:	Improving		ents are sought to the management of the vater bodies more generally.
A STAR	NEW ENTRY?:	No		
© Historic England Archive	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1000484	Contact: Christopher Laine 020 7973 3473	
	SITE NAME:	Forty Hall	Mid-to-late C18 pleasure grounds overlying C17 fo gardens focussed on Forty Hall, built 1629-36 for S Nicholas Rainton, and set within a C18 landscape p developed over a C16 royal palace and associated gardens. Owned and managed by the Local Author country park, with the Home Farm and ferme orne west (outside of the registered area) leased to a	
Contraction of the second	DESIGNATION:	Registered Park and Garden grade II, 5 LBs, part in SM, CA		
a second second	CONDITION:	Generally satisfactory but with significant localised problems		
1 and	VULNERABILITY:	Medium	horticultural co	ollege. Numerous issues affect the site,
and the second second	TREND:	Declining	particularly lap which threater	sed woodland and grassland management ns the character and legibility of the designe
A CONTRACTOR	NEW ENTRY ?:	Yes		the condition of individual features.
Historic England Archive	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1001357	Contact: Chris	stopher Laine 020 7973 3473
SITE NAME:	Church Street, E	dmonton N9		
DESIGNATION:	Conservation Area, 8 LBs		NEW ENTRY?:	No
CONDITION:	Very bad		TREND:	No significant change
VULNERABILITY:	Low		CONTACT:	Christine White (LPA) 020 8379 3852
SITE NAME:	Fore Street, Edm	onton NI8		
DESIGNATION:	Conservation Are	ea, 6 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad		TREND:	Improving

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument