

# Appendix 1

## HRD2324\_021 - Albany Park






Lot 1 – Rear of Bowling Club

Changing Rooms, showers and toilets -not included

Entrance to building from car park – Block D ex bowling club. No interconnecting doors.



Main Entrance to ex-Bowling Club view from Bowling Green – Block D – Lot 1



**Excluded** –  
Extremely poor  
condition and  
would require  
extensive  
conversion.

Main Entrance to ex-Bowling Club view  
from Bowling Green – Block D – Lot 1.  
**Included.**



*General View of the kitchen/Cafe Area –  
Block D*